



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

| | | | | | |
|-----------------------|----|------------------|----------|------------------------------|---------|
| Unique Test ID | 93 | Date: | 9/1/2004 | MeterBasin: | 01_WR23 |
| Observer ID: | A | Crew: | T-1 | Dye Test Recommended: | N |
| Defect No: | 2 | Setup No: | 1 | Priority CCTV: | |

| | | | |
|---------------------|-----------------------|---------------------|---------------------|
| House Number | Street Prefix: | Street Name: | Street Type: |
| 6105 | | Gist | AVE |

| | | | | |
|---------------------|------------------|-----------------------|--------------|------------------|
| Source Type: | 02= Service Line | Location: | 7=Yard-Front | Severity: |
| Sector: | 2=Private | Drainage Area: | 25 | |
| Comments: | hole in ground | | | |

SMOKE TEST PHOTOS



Photo No:

Filename Path:

Image Status: No image name specified.

Photo No: 2

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\0901-2004\T-1\PLAYER_A\A_2004_0901Image0002.JPG

Image Status: Image found and displayed.

Photo No:

Filename Path:


Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No: 93

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\93.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

| | | | | | |
|-----------------------|----|------------------|----------|------------------------------|---------|
| Unique Test ID | 93 | Date: | 9/1/2004 | MeterBasin: | 01_WR23 |
| Observer ID: | A | Crew: | T-1 | Dye Test Recommended: | N |
| Defect No: | 3 | Setup No: | 1 | Priority CCTV: | |

| | | | |
|---------------------|-----------------------|---------------------|---------------------|
| House Number | Street Prefix: | Street Name: | Street Type: |
| 6109 | | Gist | AVE |

| | | | | |
|---------------------|--------------|------------------|--------------|------------------|
| Source Type: | 04= Cleanout | Location: | 7=Yard-Front | Severity: |
|---------------------|--------------|------------------|--------------|------------------|

| | | | |
|----------------|-----------|-----------------------|----|
| Sector: | 2=Private | Drainage Area: | 25 |
|----------------|-----------|-----------------------|----|

Comments:

SMOKE TEST PHOTOS



Photo No:

Filename Path:

Image Status: No image name specified.

Photo No: 3

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\0901-2004\T-1\PLAYER_A\A_2004_0901Image0003.JPG

Image Status: Image found and displayed.

Photo No:

Filename Path:


Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No: 93

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\93.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

| | | | | | |
|-----------------------|----|------------------|----------|------------------------------|---------|
| Unique Test ID | 93 | Date: | 9/1/2004 | MeterBasin: | 01_WR23 |
| Observer ID: | A | Crew: | T-1 | Dye Test Recommended: | N |
| Defect No: | 4 | Setup No: | 1 | Priority CCTV: | |

| | | | |
|---------------------|-----------------------|---------------------|---------------------|
| House Number | Street Prefix: | Street Name: | Street Type: |
| 6113 | | Gist | AVE |

| | | | | |
|---------------------|--------------|-----------------------|--------------|------------------|
| Source Type: | 04= Cleanout | Location: | 7=Yard-Front | Severity: |
| Sector: | 2=Private | Drainage Area: | 0 | |

Comments:

SMOKE TEST PHOTOS



Photo No:

Filename Path:

Image Status: No image name specified.

Photo No: 4

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\0901-2004\T-1\PLAYER_A\A_2004_0901Image0004.JPG

Image Status: Image found and displayed.

Photo No:

Filename Path:


Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No: 93

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\93.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

| | | | | | |
|-----------------------|----|------------------|----------|------------------------------|---------|
| Unique Test ID | 93 | Date: | 9/1/2004 | MeterBasin: | 01_WR23 |
| Observer ID: | A | Crew: | T-1 | Dye Test Recommended: | N |
| Defect No: | 5 | Setup No: | 1 | Priority CCTV: | |

| | | | |
|---------------------|-----------------------|---------------------|---------------------|
| House Number | Street Prefix: | Street Name: | Street Type: |
| 6115 | | Gist | AVE |

| | | | | |
|---------------------|--------------|-----------------------|--------------|------------------|
| Source Type: | 04= Cleanout | Location: | 7=Yard-Front | Severity: |
| Sector: | 2=Private | Drainage Area: | 25 | |

Comments:

SMOKE TEST PHOTOS




Photo No:

Filename Path:

Image Status: No image name specified.

Photo No: 5

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\0901-2004\T-1\PLAYER_A\A_2004_0901Image0005.JPG

Image Status: Image found and displayed.

Photo No:

Filename Path:


Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No: 93

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\93.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

| | | | | | |
|-----------------------|----|------------------|----------|------------------------------|---------|
| Unique Test ID | 93 | Date: | 9/1/2004 | MeterBasin: | 01_WR23 |
| Observer ID: | A | Crew: | T-1 | Dye Test Recommended: | N |
| Defect No: | 6 | Setup No: | 1 | Priority CCTV: | |

| | | | |
|---------------------|-----------------------|---------------------|---------------------|
| House Number | Street Prefix: | Street Name: | Street Type: |
| 6114 | | Gist | AVE |

| | | | | |
|---------------------|--------------|-----------------------|--------------|------------------|
| Source Type: | 04= Cleanout | Location: | 7=Yard-Front | Severity: |
| Sector: | 2=Private | Drainage Area: | 25 | |

Comments:

SMOKE TEST PHOTOS



Photo No:

Filename Path:

Image Status: No image name specified.

Photo No: 6

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\0901-2004\T-1\PLAYER_A\A_2004_0901Image0006.JPG

Image Status: Image found and displayed.

Photo No:

Filename Path:


Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No: 93

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\93.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

| | | | | | |
|-----------------------|----|------------------|----------|------------------------------|---------|
| Unique Test ID | 93 | Date: | 9/1/2004 | MeterBasin: | 01_WR23 |
| Observer ID: | A | Crew: | T-1 | Dye Test Recommended: | N |
| Defect No: | 7 | Setup No: | 1 | Priority CCTV: | |

| | | | |
|---------------------|-----------------------|---------------------|---------------------|
| House Number | Street Prefix: | Street Name: | Street Type: |
| 3706 | | Pinkney | ROAD |

| | | | | |
|---------------------|--------------|-----------------------|-------------|------------------|
| Source Type: | 04= Cleanout | Location: | 9=Yard-Side | Severity: |
| Sector: | 2=Private | Drainage Area: | 0 | |

Comments:

SMOKE TEST PHOTOS



Photo No:

Filename Path:

Image Status: No image name specified.

Photo No: 7

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\0901-2004\T-1\PLAYER_A\A_2004_0901Image0007.JPG

Image Status: Image found and displayed.

Photo No:

Filename Path:


Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No: 93

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\93.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

| | | | | | |
|-----------------------|----|------------------|----------|------------------------------|---------|
| Unique Test ID | 93 | Date: | 9/1/2004 | MeterBasin: | 01_WR23 |
| Observer ID: | A | Crew: | T-1 | Dye Test Recommended: | N |
| Defect No: | 8 | Setup No: | 1 | Priority CCTV: | |

| | | | |
|---------------------|-----------------------|---------------------|---------------------|
| House Number | Street Prefix: | Street Name: | Street Type: |
| 6206 | | Gist | AVE |

| | | | | |
|---------------------|--------------|-----------------------|--------------|------------------|
| Source Type: | 04= Cleanout | Location: | 7=Yard-Front | Severity: |
| Sector: | 2=Private | Drainage Area: | 0 | |

Comments:

SMOKE TEST PHOTOS



Photo No:

Filename Path:

Image Status: No image name specified.

Photo No: 8

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\0901-2004\T-1\PLAYER_A\A_2004_0901Image0008.JPG

Image Status: Image found and displayed.

Photo No:

Filename Path:


Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No: 93

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\93.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

| | | | | | |
|-----------------------|----|------------------|----------|------------------------------|---------|
| Unique Test ID | 93 | Date: | 9/1/2004 | MeterBasin: | 01_WR23 |
| Observer ID: | B | Crew: | T-1 | Dye Test Recommended: | N |
| Defect No: | 1 | Setup No: | 1 | Priority CCTV: | |

| | | | |
|---------------------|-----------------------|---------------------|---------------------|
| House Number | Street Prefix: | Street Name: | Street Type: |
| 3702 | | Menlo | DR |

| | | | | |
|---------------------|--------------|-----------------------|-------------|------------------|
| Source Type: | 04= Cleanout | Location: | 8=Yard-Back | Severity: |
| Sector: | 2=Private | Drainage Area: | 10 | |

Comments:

SMOKE TEST PHOTOS



Photo No:

Filename Path:

Image Status: No image name specified.

Photo No: 1

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\0901-2004\T-1\PLAYER_B\B_2004_0901Image0001.JPG

Image Status: Image found and displayed.

Photo No:

Filename Path:


Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No: 93

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\93.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

| | | | | | |
|-----------------------|----|------------------|----------|------------------------------|---------|
| Unique Test ID | 93 | Date: | 9/1/2004 | MeterBasin: | 01_WR23 |
| Observer ID: | B | Crew: | T-1 | Dye Test Recommended: | N |
| Defect No: | 2 | Setup No: | 1 | Priority CCTV: | |

| | | | |
|---------------------|-----------------------|---------------------|---------------------|
| House Number | Street Prefix: | Street Name: | Street Type: |
| 3604 | | Menlo | DR |

| | | | | |
|---------------------|--------------|-----------------------|-------------|------------------|
| Source Type: | 04= Cleanout | Location: | 8=Yard-Back | Severity: |
| Sector: | 2=Private | Drainage Area: | 0 | |

Comments:

SMOKE TEST PHOTOS



Photo No:

Filename Path:

Image Status: No image name specified.

Photo No: 2

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\0901-2004\T-1\PLAYER_B\B_2004_0901Image0002.JPG

Image Status: Image found and displayed.

Photo No:

Filename Path:


Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No: 93

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\93.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

| | | | | | |
|-----------------------|----|------------------|----------|------------------------------|---------|
| Unique Test ID | 93 | Date: | 9/1/2004 | MeterBasin: | 01_WR23 |
| Observer ID: | B | Crew: | T-1 | Dye Test Recommended: | N |
| Defect No: | 3 | Setup No: | 1 | Priority CCTV: | |

| | | | |
|---------------------|-----------------------|---------------------|---------------------|
| House Number | Street Prefix: | Street Name: | Street Type: |
| 3604 | | Menlo | DR |

| | | | | |
|---------------------|--------------|-----------------------|-------------|------------------|
| Source Type: | 04= Cleanout | Location: | 8=Yard-Back | Severity: |
| Sector: | 2=Private | Drainage Area: | 50 | |

Comments:

SMOKE TEST PHOTOS




Photo No:

Filename Path:

Image Status: No image name specified.

Photo No: 3

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\0901-2004\T-1\PLAYER_B\B_2004_0901Image0003.JPG

Image Status: Image found and displayed.

Photo No:

Filename Path:


Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No: 93

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\93.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

| | | | | | |
|-----------------------|----|------------------|----------|------------------------------|---------|
| Unique Test ID | 93 | Date: | 9/1/2004 | MeterBasin: | 01_WR23 |
| Observer ID: | B | Crew: | T-1 | Dye Test Recommended: | N |
| Defect No: | 4 | Setup No: | 1 | Priority CCTV: | |

| | | | |
|---------------------|-----------------------|---------------------|---------------------|
| House Number | Street Prefix: | Street Name: | Street Type: |
| 3602 | | Menlo | DR |

| | | | | |
|---------------------|--------------|-----------------------|-------------|------------------|
| Source Type: | 04= Cleanout | Location: | 8=Yard-Back | Severity: |
| Sector: | 2=Private | Drainage Area: | 0 | |

Comments:

SMOKE TEST PHOTOS



Photo No:

Filename Path:

Image Status: No image name specified.

Photo No: 4

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\0901-2004\T-1\PLAYER_B\B_2004_0901Image0004.JPG

Image Status: Image found and displayed.

Photo No:

Filename Path:


Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No: 93

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\93.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

| | | | | | |
|-----------------------|----|------------------|----------|------------------------------|--------|
| Unique Test ID | 93 | Date: | 9/1/2004 | MeterBasin: | 03_31S |
| Observer ID: | B | Crew: | T-1 | Dye Test Recommended: | N |
| Defect No: | 5 | Setup No: | 1 | Priority CCTV: | |

| | | | |
|---------------------|-----------------------|---------------------|---------------------|
| House Number | Street Prefix: | Street Name: | Street Type: |
| 3706 | | Menlo | DR |

| | | | | |
|---------------------|-----------|-----------------------|-------------|------------------|
| Source Type: | 18= Other | Location: | 8=Yard-Back | Severity: |
| Sector: | 2=Private | Drainage Area: | 100 | |

Comments: source cannot be determined

SMOKE TEST PHOTOS




Photo No:

Filename Path:

Image Status: No image name specified.

Photo No: 5

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\0901-2004\T-1\PLAYER_B\B_2004_0901Image0005.JPG

Image Status: Image found and displayed.

Photo No:

Filename Path:


Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No: 93

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\93.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

| | | | | | |
|-----------------------|----|------------------|----------|------------------------------|---------|
| Unique Test ID | 94 | Date: | 9/1/2004 | MeterBasin: | 01_WR23 |
| Observer ID: | A | Crew: | T-1 | Dye Test Recommended: | Y |
| Defect No: | 1 | Setup No: | 2 | Priority CCTV: | |

| | | | |
|---------------------|-----------------------|---------------------|---------------------|
| House Number | Street Prefix: | Street Name: | Street Type: |
| 6006 | | Park Heights | AVE |

| | | | | |
|---------------------|-----------------|------------------|--------|------------------|
| Source Type: | 14= Catch Basin | Location: | 6=Curb | Severity: |
|---------------------|-----------------|------------------|--------|------------------|

| | | | |
|----------------|----------|-----------------------|-------|
| Sector: | 1=Public | Drainage Area: | 12500 |
|----------------|----------|-----------------------|-------|

Comments: intersection of streets

SMOKE TEST PHOTOS




Photo No:

Filename Path:

Image Status: No image name specified.

Photo No: 9

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\0901-2004\T-1\PLAYER_A\A_2004_0901Image0009.JPG

Image Status: Image found and displayed.

Photo No:

Filename Path:


Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No: 94

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\94.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

| | | | | | |
|-----------------------|----|------------------|----------|------------------------------|---------|
| Unique Test ID | 94 | Date: | 9/1/2004 | MeterBasin: | 01_WR23 |
| Observer ID: | A | Crew: | T-1 | Dye Test Recommended: | N |
| Defect No: | 10 | Setup No: | 2 | Priority CCTV: | |

| | | | |
|---------------------|-----------------------|---------------------|---------------------|
| House Number | Street Prefix: | Street Name: | Street Type: |
| 3502 | | Taney | ROAD |

| | | | | |
|---------------------|--------------|-----------------------|--------------|------------------|
| Source Type: | 04= Cleanout | Location: | 7=Yard-Front | Severity: |
| Sector: | 2=Private | Drainage Area: | 25 | |

Comments:

SMOKE TEST PHOTOS




Photo No:

Filename Path:

Image Status: No image name specified.

Photo No: 18

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\0901-2004\T-1\PLAYER_A\A_2004_0901Image0018.JPG

Image Status: Image found and displayed.

Photo No:

Filename Path:


Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No: 94

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\94.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

| | | | | | |
|-----------------------|----|------------------|----------|------------------------------|---------|
| Unique Test ID | 94 | Date: | 9/1/2004 | MeterBasin: | 01_WR23 |
| Observer ID: | A | Crew: | T-1 | Dye Test Recommended: | Y |
| Defect No: | 2 | Setup No: | 2 | Priority CCTV: | |

| | | | |
|---------------------|-----------------------|-----------------------|---------------------|
| House Number | Street Prefix: | Street Name: | Street Type: |
| 6006 | | Park Heights | AVE |
| Source Type: | 14= Catch Basin | Location: | 6=Curb |
| Sector: | 1=Public | Drainage Area: | 4500 |
| Severity: | | | |
| Comments: | | | |

SMOKE TEST PHOTOS



Photo No:

Filename Path:

Image Status: No image name specified.

Photo No: 0

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\0901-2004\T-1\PLAYER_A\A_2004_0901Image0033.JPG

Image Status: Image found and displayed.

Photo No:

Filename Path:


Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No:

94

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\94.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

| | | | | | |
|-----------------------|----|------------------|----------|------------------------------|---------|
| Unique Test ID | 94 | Date: | 9/1/2004 | MeterBasin: | 01_WR23 |
| Observer ID: | A | Crew: | T-1 | Dye Test Recommended: | N |
| Defect No: | 3 | Setup No: | 2 | Priority CCTV: | |

| | | | |
|---------------------|-----------------------|---------------------|---------------------|
| House Number | Street Prefix: | Street Name: | Street Type: |
| 6004 | | Wallis | AVE |

| | | | | |
|---------------------|--------------|-----------------------|-------------|------------------|
| Source Type: | 04= Cleanout | Location: | 9=Yard-Side | Severity: |
| Sector: | 2=Private | Drainage Area: | 25 | |

Comments:

SMOKE TEST PHOTOS



Photo No:

Filename Path:

Image Status: No image name specified.

Photo No: 11

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\0901-2004\T-1\PLAYER_A\A_2004_0901Image0011.JPG

Image Status: Image found and displayed.

Photo No:

Filename Path:


Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No: 94

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\94.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

| | | | | | |
|-----------------------|----|------------------|----------|------------------------------|---------|
| Unique Test ID | 94 | Date: | 9/1/2004 | MeterBasin: | 01_WR23 |
| Observer ID: | A | Crew: | T-1 | Dye Test Recommended: | Y |
| Defect No: | 4 | Setup No: | 2 | Priority CCTV: | |

| | | | |
|---------------------|-----------------------|---------------------|---------------------|
| House Number | Street Prefix: | Street Name: | Street Type: |
| 6004 | | Wallis | AVE |

| | | | | |
|---------------------|-----------------|-----------------------|--------|------------------|
| Source Type: | 14= Catch Basin | Location: | 6=Curb | Severity: |
| Sector: | 1=Public | Drainage Area: | 5200 | |

Comments:

SMOKE TEST PHOTOS



Photo No:

Filename Path:

Image Status: No image name specified.

Photo No: 12

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\0901-2004\T-1\PLAYER_A\A_2004_0901Image0012.JPG

Image Status: Image found and displayed.

Photo No:

Filename Path:


Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No: 94

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\94.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

| | | | | | |
|-----------------------|----|------------------|----------|------------------------------|---------|
| Unique Test ID | 94 | Date: | 9/1/2004 | MeterBasin: | 01_WR23 |
| Observer ID: | A | Crew: | T-1 | Dye Test Recommended: | Y |
| Defect No: | 5 | Setup No: | 2 | Priority CCTV: | |

| | | | |
|---------------------|-----------------------|---------------------|---------------------|
| House Number | Street Prefix: | Street Name: | Street Type: |
| 6005 | | Wallis | AVE |

| | | | | |
|---------------------|-----------------|-----------------------|--------|------------------|
| Source Type: | 14= Catch Basin | Location: | 6=Curb | Severity: |
| Sector: | 1=Public | Drainage Area: | 5200 | |

Comments:

SMOKE TEST PHOTOS



Photo No:

Filename Path:

Image Status: No image name specified.

Photo No: 13

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\0901-2004\T-1\PLAYER_A\A_2004_0901Image0013.JPG

Image Status: Image found and displayed.

Photo No:

Filename Path:


Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No: 94

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\94.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

| | | | | | |
|-----------------------|----|------------------|----------|------------------------------|---------|
| Unique Test ID | 94 | Date: | 9/1/2004 | MeterBasin: | 01_WR23 |
| Observer ID: | A | Crew: | T-1 | Dye Test Recommended: | N |
| Defect No: | 6 | Setup No: | 2 | Priority CCTV: | |

| | | | |
|---------------------|-----------------------|---------------------|---------------------|
| House Number | Street Prefix: | Street Name: | Street Type: |
| 6017 | | Park Heights | AVE |

| | | | | |
|---------------------|--------------|-----------------------|-------------|------------------|
| Source Type: | 04= Cleanout | Location: | 8=Yard-Back | Severity: |
| Sector: | 2=Private | Drainage Area: | 25 | |

Comments:

SMOKE TEST PHOTOS



Photo No:

Filename Path:

Image Status: No image name specified.

Photo No: 14

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\0901-2004\T-1\PLAYER_A\A_2004_0901Image0014.JPG

Image Status: Image found and displayed.

Photo No:

Filename Path:


Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No: 94

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\94.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

| | | | | | |
|-----------------------|----|------------------|----------|------------------------------|---------|
| Unique Test ID | 94 | Date: | 9/1/2004 | MeterBasin: | 01_WR23 |
| Observer ID: | A | Crew: | T-1 | Dye Test Recommended: | N |
| Defect No: | 7 | Setup No: | 2 | Priority CCTV: | |

| | | | |
|---------------------|-----------------------|---------------------|---------------------|
| House Number | Street Prefix: | Street Name: | Street Type: |
| 6017 | | Park Heights | AVE |

| | | | | |
|---------------------|--------------|-----------------------|-------------|------------------|
| Source Type: | 04= Cleanout | Location: | 8=Yard-Back | Severity: |
| Sector: | 2=Private | Drainage Area: | 25 | |

Comments:

SMOKE TEST PHOTOS



Photo No:

Filename Path:

Image Status: No image name specified.

Photo No: 15

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\0901-2004\T-1\PLAYER_A\A_2004_0901Image0015.JPG

Image Status: Image found and displayed.

Photo No:

Filename Path:


Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No: 94

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\94.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.